40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory





Date: 2022/03/11

Accreditation No.: 111TD0311-022-C01

# Certificate of Conformance for Freight Container Mechanical Seal Testing Seal Classification: High Security Seal

Customer: Unisto AG

Seestrasse 7, CH-9326 Horn, Switzerland

Name of Article: Unisto Hi-Genius

Type: Hi-Genius

Serial No.: 0000001~0000026

Specification No. : ISO 17712:2013(E) Test Dates : 2022/03/03~2022/03/11

MIRDC, Certifies that 26 samples, 5 for each test and 1 for measurements, of the seal referenced above were subjected to the following tests.

| Test Item                                | Section Number | Classification         |
|--|----------------|------------------------|
| Evidence of Tampering (Minimum Diameter) | 4.1.3          | Pass                   |
| Tensile Test                             | 5.2            | High security seal (H) |
| Shear Test                               | 5.3            | High security seal (H) |
| Bending Test                             | 5.4            | High security seal (H) |
| Impact Test room temp                    | 5.5            | High security seal (H) |
| Impact Test reduced temp                 | 5.5            | High security seal (H) |

**Results**: The above listed tests were completed with no discrepancies noted. Refer to test report number L0303022-T01 for complete details.

The test results contained herein pertain only to the specimens listed in this report. This report shall not be reproduced, except in full, without the written approval of MIRDC


| Approved          |  |
|-------------------|--|
| Signatory:        |  |
| CHIANG, Ching-Liu |  |
|                   |  |
|                   |  |
| Engineer:         |  |
| SU, Yuan-Da       |  |
|                   |  |
|                   |  |
|                   |  |
|                   |  |





40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory





Test Report No. : L0303022-T01 Page 1 of 10

Customer: Unisto AG

Seestrasse 7, CH-9326 Horn, Switzerland

SUBJECT: Freight containers Mechanical seals classification Testing

Name of Article: Unisto Hi-Genius

Type: Hi-Genius

Received Date: 2022/03/03

Test Dates: 2022/03/03~2022/03/11

Date Issued: 2022/03/11

CHIANG, Ching-Liu SU, Yuan-Da 報告簽署人 (Report Authorized Person) 檢驗員 (Inspector)

Note: (1) The operation and testing of MIRDC laboratory are in conformity to the requirements of ISO/IEC 17025: 2017

(Taiwan Accreditation Foundation, Accreditation No.: 0099)

- (2) This report is responsible for designated samples only.
- (3) Reproduction of all or parts this report without a written approval is strictly prohibited.
- (4) Decision rules of conformance statement of this test report, do not consider uncertainty of measurement.



40768 台中市工業區 37 路 25 號 TEL: (04)23502169
Metal Industries Research & Development Centre

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No.: L0303022-T01 Page 2 of 10

#### 1. ABSTRACT

Customer: Unisto AG

Seestrasse 7, CH-9326 Horn, Switzerland

Name of Article: Unisto Hi-Genius

Type: Hi-Genius

Serial No.: 0000001~0000026

Quantity Tested: 26

Inspection Reference: ISO 17712:2013(E)

| Test Item                                | Section Number | Serial No.      | Results    |
|--|----------------|-----------------|------------|
| Evidence of Tampering (Minimum Diameter) | 4.1.3          | 0000026         | See Page 3 |
| Tensile Test                             | 5.2            | 0000001~0000005 | See Page 4 |
| Shear Test                               | 5.3            | 0000006~0000010 | See Page 6 |
| Bending Test                             | 5.4            | 0000011~0000015 | See Page 7 |
| Impact Test room temp                    | 5.5            | 0000016~0000020 | See Page 8 |
| Impact Test reduced temp                 | 5.5            | 0000021~0000025 | See Page 8 |

# MADO

# 財團法人金屬工業研究發展中心 機械測試實驗室

40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No.: L0303022-T01 Page 3 of 10

2. Evidence of tampering Test:

Ambient Temp. : 21°C ; 54% R.H.

Inspection Reference: ISO 17712:2013(E)

Result:

### **Evidence of tampering Section 4.1.3**

| Specimen No. | Mea       | Pass/Fail |      |
|--------------|-----------|-----------|------|
| 0000026      | Pin Head  | 19.15     | Pass |
| 0000026      | Lock Body | 18.13     | Pass |

#### Requirement:

The minimum diameter (or minimum widest cross-dimension) for the metal components of a bolt seal shall be 18 mm.







Lock Body

# MINDS

# 財團法人金屬工業研究發展中心 機械測試實驗室

40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No. : L0303022-T01 Page 4 of 10

3. Tensile Test:

Testing Instrument: Universal Testing Machine (No.TG0103)

Ambient Temp. : 21°C ; 54% R.H

Inspection Reference: ISO 17712:2013(E)

Result:

#### **Tensile Test Section 5.2**

The seal was gripped in a tensile machine and a pull force applied.

| Specimen No. | Requirement<br>Load to failure  | Result<br>kN | Seal classification    |
|--------------|---|--------------|------------------------|
| 0000001      | 10.0 kN: High security seal 2.27 kN: Security seal < 2.27 kN: Indicative seal | 18.3         | High security seal (H) |
| 0000002      |   | 17.8         | High security seal (H) |
| 0000003      |   | 17.3         | High security seal (H) |
| 0000004      |   | 16.2         | High security seal (H) |
| 0000005      |   | 17.8         | High security seal (H) |



40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No. : L0303022-T01 Page 5 of 10

### Universal Testing Machine



Tensile Set up





40768 台中市工業區 37 路 25 號 TEL: (04)23502169 Metal Industries Research & Development Centre

#### etal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No. : L0303022-T01 Page 6 of 10

4. Shear Test

Testing Instrument: Universal Testing Machine (No.TG0103)

Ambient Temp. :  $21^{\circ}$ C ; 54% R.H.

Inspection Reference: ISO 17712:2013(E)

Result:

#### **Shear Test Section 5.3**

The seal was fixed in a universal testing machine to withstand cutting with shearing blades and a compressive load applied slowly until the seal is severed.

| Specimen No. | Requirement Load to failure   | Result<br>kN | Seal classification    |
|--------------|---|--------------|------------------------|
| 0000006      | 3.336 kN: High security seal 2.224 kN: Security seal <2.224 kN: Indicative seal | 8.896        | High security seal (H) |
| 0000007      |   | 8.896        | High security seal (H) |
| 0000008      |   | 8.896        | High security seal (H) |
| 0000009      |   | 8.896        | High security seal (H) |
| 0000010      |   | 8.896        | High security seal (H) |

Shear Set up



SAFETY PRECAUTIONS - Do not exceed a shear force greater than 8900N(2001lbf). If the specimen has not failed at that force, halt the test and unload the test equipment. Record a shear force of 8896N (2000 lbf). Sudden and violent rupture of the test specimen can endanger personnel, equipment and property.



40768 台中市工業區 37 路 25 號 TEL: (04)23502169

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No.: L0303022-T01 Page 7 of 10

#### 5. Bending Test

Testing Instrument : FORCE GAURE Ambient Temp. : 21°C ; 54% R.H


Inspection Reference: ISO 17712:2013(E)

Result:

#### **Bending Test Section 5.4**

Fix the locking end on the universal testing machine in a horizontal position. Apply a load on the remaining portion of the seal at a distance (the moment arm) above the fixed end so as to bend the seal 90 degrees.

| Specimen No. | Requirement Bending moment to failure   | Result<br>Nm | Seal classification    |
|--------------|---|--------------|------------------------|
| 0000011      | 50 Nm: High security seal<br>22 Nm: Security seal<br>< 22 Nm: Indicative seal | 53.7         | High security seal (H) |
| 0000012      |   | 52.2         | High security seal (H) |
| 0000013      |   | 51.5         | High security seal (H) |
| 0000014      |   | 51.6         | High security seal (H) |
| 0000015      |   | 53.3         | High security seal (H) |



Bend Set up



40768 台中市工業區 37 路 25 號 TEL: (04)23502169 Metal Industries Research & Development Centre

Mechanical Testing Laboratory No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No.: L0303022-T01 Page 8 of 10

#### 6. Impact Test

Testing Instrument:

1. Impact Tester

2. Programmable Low Temp. Tester (No.SG5501)

Inspection Reference: ISO 17712:2013(E)

#### **Impact Test Section 5.5**

The impact test is performed at 18 degrees C and minus 27 degrees C of temperature. The impact load is applied at the locking mechanism of the seal in the direction opposite the direction used in locking the seal.

#### Result:

| Impact Test a | Impact Test at 18 ℃                            |                 |       |       |                        |
|---------------|--|-----------------|-------|-------|------------------------|
| Specimen No.  | Requirement                                    | Result<br>Joule |       |       | Seal classification    |
|               |  | 13.56           | 27.12 | 40.68 |                        |
| 0000016       |  | Pass            | Pass  | Pass  | High security seal (H) |
| 0000017       | 40.68J: High security seal                     | Pass            | Pass  | Pass  | High security seal (H) |
| 0000018       | 27.12J: Security seal <27.12J: Indicative seal | Pass            | Pass  | Pass  | High security seal (H) |
| 0000019       | 5 impacts at each load                         | Pass            | Pass  | Pass  | High security seal (H) |
| 0000020       |  | Pass            | Pass  | Pass  | High security seal (H) |

| Impact Test at -27 °C |   |                 |       |       |                        |
|-----------------------|---|-----------------|-------|-------|------------------------|
| Specimen No.          | Requirement   | Result<br>Joule |       |       | Seal classification    |
|                       |   | 13.56           | 27.12 | 40.68 |                        |
| 0000021               | 40.68J: High security seal<br>27.12J: Security seal<br><27.12J: Indicative seal<br>5 impacts at each load | Pass            | Pass  | Pass  | High security seal (H) |
| 0000022               |   | Pass            | Pass  | Pass  | High security seal (H) |
| 0000023               |   | Pass            | Pass  | Pass  | High security seal (H) |
| 0000024               |   | Pass            | Pass  | Pass  | High security seal (H) |
| 0000025               |   | Pass            | Pass  | Pass  | High security seal (H) |



40768 台中市工業區 37 路 25 號 TEL: (04)23502169 Metal Industries Research & Development Centre

#### Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No. : L0303022-T01 Page 9 of 10



Impact Set up



40768 台中市工業區 37 路 25 號 TEL: (04)23502169 Metal Industries Research & Development Centre

1etal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Test Report No. L0303022-T01

Page 10 of 10



Name of Article: Unisto Hi-Genius

Type: Hi-Genius

---End---



40768 台中市工業區 37 路 25 號 TEL: (04)23502169 Metal Industries Research & Development Centre Mechanical Testing Laboratory

No.25, 37th Road, Industrial Park, Taichung City 40768, Taiwan (R.O.C.) 試驗報告 TEST REPORT

Customer : Unisto AG

Seestrasse 7, CH-9326 Horn, Switzerland

檢 測 編 號:L0303022-T02

Application No

收件日期:2022/03/03

Received Date

試驗日期:2022/03/10

Test Date

簽 發 日 期:2022/03/11

Date Issued Page 1 of 1

(1).試樣名稱 Name of Article: Unisto Hi-Genius 型號 Type: Hi-Genius

(2).試驗項目 Test Item: 抗旋轉測試 Anti rotation test

(3).測試規範 Inspection Reference: CNS 17712 (2014) 5.1.2

(4).測試方法 Testing method:子彈型封條以手動進行扭轉測試,於鎖桿插入鎖座扣合上鎖後,組合元件於未使用

工具時,以相反方向旋轉或扭轉。

The Bolt seals will undergo rotation test manually. And after the locking mechanism of the seal is locked, it will be turned or twisted in opposite direction by hand without

using any tools.

(5).試驗結果 Result:

| 抗扭轉           | 扭轉角度           |             |  |
|---------------|----------------|-------------|--|
| Anti-rotation | Rotation angle |             |  |
| 有效/無效         | 測試值            | 規範要求        |  |
| Valid /fail   | Test result    | Requirement |  |
| 有效 Valid      | 22°            | <360°       |  |

判定:符合抗旋轉要求(合格)。

Conclusion: The test sample met the requirement of anti-rotation regulation (Qualified).

原樣品 Sample



--- End ---

注意:(1)本報告僅對送檢樣品負責。(2)本報告未經書面許可不得複製或摘錄。

(3)本測試報告的符合性聲明之判定規則,不考慮測量不確定度。

Note: (1) This report is responsible for designated samples only.

(2) Reproduction of all or parts this report without a written approval is strictly prohibited.

(3) Decision rules of conformance statement of this test report, do not consider uncertainty of measurement.

報告簽署人: Report Authorized Person CHIANG, Ching-Liu

檢驗員: Inspector SU, Yuan-Da